

Arista Access Switch SOP for Alarm Code

ALARM_7557

Node: Arista-Access-Mumbai-MH-56 | **Vendor:** Arista | **Severity:** Major | **Alarm Code:** ALARM_7557

Description

This SOP outlines the procedures to diagnose and resolve the ALARM_7557 (High CPU Utilization) on the Arista Access Switch Node ID: Arista-Access-Mumbai-MH-56.

Potential Root Causes

Cause	Probability
High CPU Utilization due to excessive packet processing	High
Insufficient resources (CPU/Memory) on the switch	Medium
Misconfigured or malfunctioning software features	Low

Diagnostic Commands

```
show system resources
show cpu status
show memory status
show process cpu
show process memory
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU and Memory Utilization', 'Action': 'Run the show system resources command to check CPU and Memory Utilization.'}
- Step 2: {'Step': '2. Verify CPU and Memory Resources', 'Action': 'Verify if CPU and Memory resources are sufficient for the switch. If not, consider upgrading resources or adjusting system settings.'}
- Step 3: {'Step': '3. Check for Misconfigured or Malfunctioning Software Features', 'Action': 'Run the show process cpu and show process memory commands to identify any misconfigured or malfunctioning software features.'}
- Step 4: {'Step': '4. Adjust System Settings or Upgrade Resources', 'Action': 'Adjust system settings or upgrade resources to resolve the issue.'}

Post-Check Verification

```
show system resources
```

```
show cpu status  
show memory status
```