

Arista Access Switch ALARM_9347: Warning - Mumbai-MH-56

Node: Arista-Access-Mumbai-MH-56 | **Vendor:** Arista | **Severity:** Warning | **Alarm Code:** ALARM_9347

Description

This SOP outlines the steps to identify, diagnose, and resolve the ALARM_9347 warning on Arista Access Switch Node ID: Arista-Access-Mumbai-MH-56.

Potential Root Causes

Cause	Probability
Buffer overflow due to excessive traffic on port 1/1/1	High
Misconfigured spanning tree protocol on port 1/1/1	Medium
Hardware fault on port 1/1/1	Low

Diagnostic Commands

```
show system info
show interface 1/1/1
show spanning-tree detail
show buffer statistics
```

Resolution Steps

Step 1: {'Step': 'Clear buffer overflow', 'Action': 'Clear buffer statistics using the command: clear buffer statistics'}

Step 2: {'Step': 'Reconfigure spanning tree protocol', 'Action': 'Reconfigure spanning tree protocol using the command: spanning-tree config '}

Step 3: {'Step': 'Replace hardware on port 1/1/1', 'Action': 'Replace the hardware on port 1/1/1 and verify the issue is resolved'}

Post-Check Verification

```
show system info
show interface 1/1/1
show spanning-tree detail
show buffer statistics
```