

Arista PE Bangalore KA 76 - Alarm Code

ALARM_3079: Minor

Node: Arista-PE-Bangalore-KA-76 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM_3079

Description

Alarm Code ALARM_3079 indicates a minor issue with the Arista PE Bangalore KA 76 Provider Edge Router.

Potential Root Causes

Cause	Probability
Incorrect OSPF configuration	Medium
Aging or faulty interface	Low
Routing protocol inconsistencies	Medium

Diagnostic Commands

```
show ip ospf interface
show ip interface
show ip route
show routing-table ospf
```

Resolution Steps

- Step 1: {'Step': 'Verify OSPF configuration', 'Action': "Run the command 'show run | include ospf' and ensure OSPF configuration is correct."}
- Step 2: {'Step': 'Check interface status', 'Action': "Run the command 'show ip interface' and verify the interface status is up."}
- Step 3: {'Step': 'Clear OSPF cache', 'Action': "Run the command 'clear ip ospf process' to clear OSPF cache."}
- Step 4: {'Step': 'Verify routing table', 'Action': "Run the command 'show ip route' and verify the routing table is up-to-date."}

Post-Check Verification

```
show ip interface
show ip ospf interface
show ip route
```

```
show routing-table ospf
```