

Arista PE Router - Alarm Code ALARM_8764 SOP

Node: Arista-PE-Bangalore-KA-76 | **Vendor:** Arista | **Severity:** Warning | **Alarm Code:** ALARM_8764

Description

This SOP outlines the procedures for addressing a Warning severity ALARM_8764 on the Arista PE Router, Bangalore KA 76.

Potential Root Causes

Cause	Probability
Buffer Overflow Error	High
Incorrect Configuration	Medium
Hardware Failure	Low

Diagnostic Commands

```
show system internal buffer
show config | i buffer-size
show hardware
show version
```

Resolution Steps

- Step 1: {'Step': 'Verify Buffer Overflow', 'Action': "Run the command 'show system internal buffer' to check for buffer overflow errors."}
- Step 2: {'Step': 'Adjust Buffer Size', 'Action': "Run the command 'config terminal', then 'buffer-size ' to adjust the buffer size."}
- Step 3: {'Step': 'Re-Verify Configuration', 'Action': "Run the command 'show config | i buffer-size' to verify the buffer size has been adjusted."}
- Step 4: {'Step': 'Verify Hardware', 'Action': "Run the command 'show hardware' to verify there are no hardware issues."}
- Step 5: {'Step': 'Verify Version', 'Action': "Run the command 'show version' to verify the software version."}

Post-Check Verification

```
show alarm
show system internal buffer
```

```
show config | i buffer-size
```