

Arista PE Bangalore KA-81 - Alarm 2241 Resolution SOP

Node: Arista-PE-Bangalore-KA-81 | **Vendor:** Arista | **Severity:** Critical | **Alarm Code:** ALARM_2241

Description

Critical alarm on Provider Edge Router Arista-PE-Bangalore-KA-81 due to Alarm Code ALARM_2241

Potential Root Causes

Cause	Probability
Faulty Transceiver Module	High
Software Configuration Issue	Medium
Hardware Failure	Low

Diagnostic Commands

```
show transceiver
show interface
show log
show system resource
show tech-support
```

Resolution Steps

- Step 1: {'Step': '1. Power cycle the router', 'Action': "Enter 'shutdown' and 'no shutdown' command on the interface"}
- Step 2: {'Step': '2. Replace the faulty transceiver module', 'Action': "Enter 'replace-transceiver' command on the interface"}
- Step 3: {'Step': '3. Verify software configuration', 'Action': "Enter 'show running-config' command"}
- Step 4: {'Step': '4. Reboot the router', 'Action': "Enter 'reload' command"}

Post-Check Verification

```
show interface
show log
show system resource
show tech-support
```