

Arista PE Bangalore KA-81 Alarm 3443 Minor Resolution SOP

Node: Arista-PE-Bangalore-KA-81 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM_3443

Description

This SOP outlines the steps to diagnose and resolve the ALARM_3443 Minor alarm on the Arista PE Bangalore KA-81 Provider Edge Router.

Potential Root Causes

Cause	Probability
High CPU utilization due to excessive routing protocols configuration	High
Interface flapping due to hardware issues	Medium
Misconfigured routing policies	Low

Diagnostic Commands

```
show system resource cpu
show interface status
show bgp summary
show ip route
show routing-policy
```

Resolution Steps

- Step 1: {'Step': 'Verify CPU utilization levels', 'Action': "Check the output of 'show system resource cpu' command and ensure that the CPU utilization is within normal limits (< 50%)"}
Step 2: {'Step': 'Troubleshoot interface flapping', 'Action': "Run 'show interface status' command to identify the interface causing the flapping and replace the faulty interface if necessary"}
Step 3: {'Step': 'Review routing policies', 'Action': "Check the output of 'show routing-policy' command to ensure that the routing policies are correctly configured"}
Step 4: {'Step': 'Clear the alarm', 'Action': "Run 'clear alarm 3443' command to clear the alarm on the device"}

Post-Check Verification

```
show alarm 3443
show system resource cpu
```

```
show interface status
```