

Arista PE Router Mumbai-MH-52 Alarm Resolution SOP (ALARM_1904)

Node: Arista-PE-Mumbai-MH-52 | **Vendor:** Arista | **Severity:** Major | **Alarm Code:** ALARM_1904

Description

Major Alarm on Arista PE Router Mumbai-MH-52 - Investigate and resolve the issue to prevent network downtime.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Misconfigured BGP Session	Medium
Hardware Failure	Low

Diagnostic Commands

```
show system resources
show bgp summary
show bgp neighbors
show system internal cpu-usage
show system internal memory-usage
```

Resolution Steps

- Step 1: {'Step': 'Verify BGP Session Configuration', 'Action': "Run command 'show bgp summary' to verify BGP session status. If BGP session is down, follow step 2.", 'CLI_Command': 'show bgp summary'}
- Step 2: {'Step': 'Re-Configure BGP Session', 'Action': "Run command 'config t', then 'router bgp 65000', followed by 'neighbor remote-as 65000' to re-configure BGP session.", 'CLI_Command': ['config t', 'router bgp 65000', 'neighbor remote-as 65000']}
- Step 3: {'Step': 'Check for Hardware Failure', 'Action': "Run command 'show system internal cpu-usage' and 'show system internal memory-usage' to check for hardware failure. If issue persists, initiate hardware replacement.", 'CLI_Command': ['show system internal cpu-usage', 'show system internal memory-usage']}

Post-Check Verification

```
show bgp summary
```

```
show system resources
show system internal cpu-usage
```