

# Standard Operating Procedure for Resolving ALARM\_2179 on Arista-PE-Mumbai-MH-52

**Node:** Arista-PE-Mumbai-MH-52 | **Vendor:** Arista | **Severity:** Major | **Alarm Code:** ALARM\_2179

## Description

This SOP outlines the steps to diagnose and resolve the ALARM\_2179 error on the Arista-PE-Mumbai-MH-52 Provider Edge Router.

## Potential Root Causes

| Cause                  | Probability |
|------------------------|-------------|
| Hardware Failure       | High        |
| Software Bug           | Medium      |
| Configuration Mismatch | Low         |

## Diagnostic Commands

```
show system resource
show hardware
show version
show running-config
debug protocol bgp
```

## Resolution Steps

- Step 1: {'Step': '1. Check System Resources', 'Action': "Run the command 'show system resource' to verify that the system has sufficient resources.", 'CLI\_Command': 'show system resource'}
- Step 2: {'Step': '2. Verify Hardware Integrity', 'Action': "Use the command 'show hardware' to check for any hardware issues.", 'CLI\_Command': 'show hardware'}
- Step 3: {'Step': '3. Check Software Version', 'Action': "Run the command 'show version' to verify that the software is up-to-date.", 'CLI\_Command': 'show version'}
- Step 4: {'Step': '4. Review Configuration', 'Action': "Use the command 'show running-config' to verify that the configuration is correct.", 'CLI\_Command': 'show running-config'}
- Step 5: {'Step': '5. Debug BGP Protocol', 'Action': "Run the command 'debug protocol bgp' to troubleshoot BGP issues.", 'CLI\_Command': 'debug protocol bgp'}
- Step 6: {'Step': '6. Reset the Router', 'Action': 'If all previous steps do not resolve the issue, reset the router to its default state.', 'CLI\_Command': 'reload'}

## Post-Check Verification

```
show system resource  
show hardware  
show version  
show running-config
```