

Arista PE Router Alarm Resolution SOP - ALARM_6001

Node: Arista-PE-Mumbai-MH-52 | **Vendor:** Arista | **Severity:** Major | **Alarm Code:** ALARM_6001

Description

This SOP details the steps to diagnose and resolve the ALARM_6001 error on the Arista PE Router, Arista-PE-Mumbai-MH-52.

Potential Root Causes

Cause	Probability
High CPU Utilization on the Router	High
Software or Configuration Errors	Medium
Hardware Issues (e.g., Fan Failure, Power Supply Failure)	Low

Diagnostic Commands

```
show system resources
show processes cpu
show system logging
show system software
show interface status
```

Resolution Steps

Step 1: {'Step': 'Step 1: Check CPU Utilization', 'Description': 'Verify CPU utilization levels on the router.', 'Action': [{'Command': 'show system resources', 'Description': 'Check CPU utilization levels using this command.'}]}

Step 2: {'Step': 'Step 2: Investigate Software or Configuration Errors', 'Description': 'Verify that there are no software or configuration errors on the router.', 'Action': [{'Command': 'show system software', 'Description': 'Check the router's software version and configuration file.'}, {'Command': 'show system logging', 'Description': 'Verify that there are no error logs on the router.'}]}

Step 3: {'Step': 'Step 3: Check for Hardware Issues', 'Description': 'Verify that there are no hardware issues on the router.', 'Action': [{'Command': 'show system hardware', 'Description': 'Verify that all hardware components are functioning properly.'}]}

Step 4: {'Step': 'Step 4: Reset the Router', 'Description': 'Reset the router to its default settings.', 'Action': [{'Command': 'reload', 'Description': 'Reset the router using this command.'}]}

Step 5: {'Step': 'Step 5: Verify the Fix', 'Description': 'Verify that the ALARM_6001 error is resolved.', 'Action': [{'Command': 'show system resources', 'Description': 'Verify CPU utilization levels using this command.'}, {'Command': 'show system software', 'Description': 'Verify that the router's software version and configuration file are correct.'}]}

Post-Check Verification

```
show system resources
show system software
```