

Arista PE Mumbai Minor Alarm Resolution SOP

Node: Arista-PE-Mumbai-MH-52 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM_7627

Description

This Standard Operating Procedure outlines the steps to resolve the ALARM_7627 minor alarm on Arista-PE-Mumbai-MH-52, a Provider Edge Router.

Potential Root Causes

Cause	Probability
Interface Link Down	High
Neighbor Not Up	Medium
Invalid Configuration	Low

Diagnostic Commands

```
show interface status
show ip bgp summary
show ip ospf neighbor detail
```

Resolution Steps

Step 1: {'Step': 'Verify interface status', 'Action': "Run the command 'show interface status' to check for any interface issues.", 'CLI_Command': 'show interface status'}

Step 2: {'Step': 'Check neighbor status', 'Action': "Run the command 'show ip bgp summary' to verify if the neighbor is up.", 'CLI_Command': 'show ip bgp summary'}

Step 3: {'Step': 'Review configuration', 'Action': 'Verify the configuration for any errors or inconsistencies.', 'CLI_Command': 'show run'}

Step 4: {'Step': 'Reboot the device', 'Action': 'Reboot the device to ensure a clean startup.', 'CLI_Command': 'reload'}

Post-Check Verification

```
show interface status
show ip bgp summary
show ip ospf neighbor detail
```