

Arista PE Router Alarm Resolution SOP - ALARM_8929

Node: Arista-PE-Mumbai-MH-52 | **Vendor:** Arista | **Severity:** Major | **Alarm Code:** ALARM_8929

Description

This SOP outlines the steps to identify and resolve a major alarm on Arista PE Router Node ID: Arista-PE-Mumbai-MH-52.

Potential Root Causes

Cause	Probability
High CPU utilization due to misconfigured routing protocols	High
Misconfigured BGP sessions	Medium
Hardware failure or malfunction	Low

Diagnostic Commands

```
show system resources cpu
show system resources memory
show ip bgp summary
show bgp neighbors
show running-config
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU utilization and adjust routing protocols configuration if necessary', 'Action': "show system resources cpu | grep -i cpu | awk '{print \$1}' | sed 's/%//'"}
- Step 2: {'Step': '2. Verify BGP sessions and adjust configuration if necessary', 'Action': 'show ip bgp summary | grep -i established'}
- Step 3: {'Step': '3. Check for hardware failure or malfunction', 'Action': 'show hardware | grep -i status'}
- Step 4: {'Step': '4. Clear BGP sessions and restart BGP process', 'Action': 'clear bgp *', 'Precondition': 'Verify that no other connections are affected'}
- Step 5: {'Step': '5. Reboot the node if necessary', 'Action': 'reboot'}

Post-Check Verification

```
show system resources cpu | grep -i cpu | awk '{print $1}' | sed 's/%//'
```

```
show ip bgp summary | grep -i established  
show hardware | grep -i status
```