

Arista PE Router Mumbai Node (52) Major Alarm SOP

Node: Arista-PE-Mumbai-MH-52 | **Vendor:** Arista | **Severity:** Major | **Alarm Code:** ALARM_9025

Description

Standard Operating Procedure for resolving Major Alarm ALARM_9025 on Arista PE Router (Mumbai Node ID: Arista-PE-Mumbai-MH-52)

Potential Root Causes

Cause	Probability
Hardware Failure (e.g. CPU, Memory, or Interface issue)	High
Software Bug or Misconfiguration	Medium
Network Congestion or Overload	Low

Diagnostic Commands

```
show system resource
show interface detail
show hardware
show version
show log
```

Resolution Steps

- Step 1: {'Step': '1. Verify Alarm Severity', 'Action': "Check the alarm severity using the command 'show alarm'", 'Notes': 'Verify that the alarm is indeed Major (Severity: Major)'}
- Step 2: {'Step': '2. Gather System Information', 'Action': "Run the command 'show system resource' to gather system resource utilization data", 'Notes': 'Note any system resource utilization issues'}
- Step 3: {'Step': '3. Inspect Interfaces', 'Action': "Run the command 'show interface detail' to inspect interface configuration and statistics", 'Notes': 'Check for any interface-related issues'}
- Step 4: {'Step': '4. Investigate Hardware', 'Action': "Run the command 'show hardware' to inspect hardware components and their status", 'Notes': 'Look for any hardware-related issues'}
- Step 5: {'Step': '5. Review System Logs', 'Action': "Run the command 'show log' to review system logs for any error messages or warnings", 'Notes': 'Note any system log errors or warnings'}
- Step 6: {'Step': '6. Reset System (if necessary)', 'Action': "Reset the system using the command 'reload' (if applicable)", 'Notes': "Resetting the system may resolve the issue if it's caused by a software bug or misconfiguration"}

Post-Check Verification

```
show alarm
show system resource
show interface detail
show hardware
show version
```