

SOP: Resolving Alarm ALARM_5183 on Cisco Access Switches in Bangalore-KA-70 Location

Node: Cisco-Access-Bangalore-KA-70 | **Vendor:** Cisco | **Severity:** Minor | **Alarm Code:** ALARM_5183

Description

Resolving Minor Alarm 5183 on Cisco Access Switches in Bangalore-KA-70 location

Potential Root Causes

Cause	Probability
Misconfigured Spanning Tree Protocol (STP)	High
Incorrect VLAN configuration	Medium
Switch hardware failure	Low

Diagnostic Commands

```
show spanning-tree detail
show vlan
show interface status
show tech-support
```

Resolution Steps

Step 1: {'Step': '1', 'Action': 'Verify STP configuration and correct if necessary', 'CLI_Command': 'spanning-tree mode {dot1d|dot1q}'}

Step 2: {'Step': '2', 'Action': 'Verify VLAN configuration and correct if necessary', 'CLI_Command': 'vlan database'}

Step 3: {'Step': '3', 'Action': 'Perform a switch reload if necessary', 'CLI_Command': 'reload'}

Post-Check Verification

```
show spanning-tree status
show vlan brief
show interface status
show tech-support
```