

SOP for Resolving Major Alarm ALARM_5657 on Cisco Access Switch Bangalore KA-70

Node: Cisco-Access-Bangalore-KA-70 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_5657

Description

This SOP outlines the steps to identify and resolve a major alarm on the Cisco Access Switch Bangalore KA-70, triggered by the alarm code ALARM_5657.

Potential Root Causes

Cause	Probability
High CPU Utilization due to Software Bugs	High
Misconfigured VLANs or Spanning Tree Protocol	Medium
Hardware Failure or Aging Components	Low

Diagnostic Commands

```
show processes cpu | include System
show spanning-tree detail
show vlan brief
show interface status | include err
```

Resolution Steps

- Step 1: {'Step': '1. Check for software bugs and update firmware if necessary.', 'Action': "Run the command 'show version' to check for firmware updates."}
- Step 2: {'Step': '2. Verify VLAN and Spanning Tree Protocol configuration.', 'Action': "Run the command 'show vlan brief' and 'show spanning-tree detail' to verify configuration."}
- Step 3: {'Step': '3. Check for hardware failures or aging components.', 'Action': "Run the command 'show interface status | include err' to check for hardware issues."}
- Step 4: {'Step': '4. If root cause is software bug, reload the switch.', 'Action': "Run the command 'reload' to restart the switch."}

Post-Check Verification

```
show processes cpu | include System
show spanning-tree detail
show vlan brief
```

```
show interface status | include err
```