

SOP: Troubleshooting Cisco Access Switch

Bangalore KA-70 - ALARM_9571

Node: Cisco-Access-Bangalore-KA-70 | **Vendor:** Cisco | **Severity:** Minor | **Alarm Code:** ALARM_9571

Description

This Standard Operating Procedure (SOP) outlines the steps to troubleshoot and resolve the ALARM_9571 on the Cisco Access Switch Bangalore KA-70. The alarm is of minor severity and is triggered by a specific vendor issue.

Potential Root Causes

Cause	Probability
Incorrect configuration or mismatched switch modules	Medium
Faulty or malfunctioning switch module	Low
Interoperability issue with connected devices	Low

Diagnostic Commands

```
show module
show version
show controllers
show interfaces
```

Resolution Steps

- Step 1: {'Step': '1. Check the switch module configuration', 'Action': "Run the command 'show module' to verify the switch module configuration.", 'CLI_Command': 'show module'}
- Step 2: {'Step': '2. Verify the switch module compatibility', 'Action': 'Check the switch module compatibility with the switch firmware.', 'CLI_Command': 'show version'}
- Step 3: {'Step': '3. Replace the faulty switch module', 'Action': 'Replace the faulty switch module with a compatible one.', 'CLI_Command': None}
- Step 4: {'Step': '4. Reset the switch module configuration', 'Action': 'Reset the switch module configuration to default values.', 'CLI_Command': 'copy start running config'}
- Step 5: {'Step': '5. Verify the switch module operation', 'Action': 'Verify the switch module operation after the above steps.', 'CLI_Command': 'show module'}

Post-Check Verification

```
show module
show version
show controllers
show interfaces
```