

Cisco Access Switch Alarm SOP: ALARM_5901

Node: Cisco-Access-Bangalore-KA-72 | **Vendor:** Cisco | **Severity:** Minor | **Alarm Code:** ALARM_5901

Description

This SOP outlines the steps to diagnose and resolve the "ALARM_5901" minor alarm on the Cisco Access Switch at Node ID: Cisco-Access-Bangalore-KA-72.

Potential Root Causes

Cause	Probability
Spanning Tree Protocol (STP) issue	Medium
Catalyst 6500 series switch hardware failure	Low
Network congestion or misconfigured switch ports	High

Diagnostic Commands

```
show spanning-tree detail
show interface status
show interface detail
show tech-support
```

Resolution Steps

- Step 1: {'Step': 'Verify the STP configuration', 'Action': 'show spanning-tree detail'}
- Step 2: {'Step': 'Check for network congestion', 'Action': 'show interface status'}
- Step 3: {'Step': 'Verify switch port configurations', 'Action': 'show interface detail'}
- Step 4: {'Step': 'Restart the switch', 'Action': 'reload'}
- Step 5: {'Step': 'Verify the ALARM_5901 status', 'Action': 'show alarm-detail'}

Post-Check Verification

```
show spanning-tree detail
show interface status
show alarm-detail
```