

SOP for Resolving Major Alarm ALARM_5913 on Cisco Access Switch in Bangalore

Node: Cisco-Access-Bangalore-KA-72 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_5913

Description

This SOP outlines the procedures to diagnose and resolve the Major Alarm ALARM_5913 on Cisco Access Switch (Node ID: Cisco-Access-Bangalore-KA-72)

Potential Root Causes

Cause	Probability
Invalid VLAN configuration	High
Misconfigured trunk port	Medium
Hardware failure	Low

Diagnostic Commands

```
show spanning-tree summary
show vlan
show interfaces trunk
show interface status
```

Resolution Steps

- Step 1: {'Step': '1. Check VLAN configuration', 'Action': 'Verify VLAN configuration using the command "show vlan"', 'CLI_Commands': 'show vlan'}
- Step 2: {'Step': '2. Check trunk port configuration', 'Action': 'Verify trunk port configuration using the command "show interfaces trunk"', 'CLI_Commands': 'show interfaces trunk'}
- Step 3: {'Step': '3. Check hardware status', 'Action': 'Verify hardware status using the command "show interface status"', 'CLI_Commands': 'show interface status'}
- Step 4: {'Step': '4. Correct VLAN configuration', 'Action': 'Correct VLAN configuration as needed', 'CLI_Commands': 'config t\nvlan database\n'}
- Step 5: {'Step': '5. Correct trunk port configuration', 'Action': 'Correct trunk port configuration as needed', 'CLI_Commands': 'config t\ninterface GigabitEthernet0/1\nswitchport trunk encapsulation dot1q\n'}
- Step 6: {'Step': '6. Replace hardware if hardware failure is confirmed', 'Action': 'Replace hardware as needed', 'CLI_Commands': ''}

Post-Check Verification

```
show spanning-tree summary
show vlan
show interfaces trunk
show interface status
```