

Cisco Access Switch Node Bangalore KA 72 Alarm SOP

Node: Cisco-Access-Bangalore-KA-72 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_7084

Description

This SOP outlines the procedures to diagnose and resolve the ALARM_7084 major alarm on the Cisco Access Switch Node Bangalore KA 72.

Potential Root Causes

Cause	Probability
Port failure due to fiber cut	High
Software issue with the switch's routing protocol	Medium
Cable damage or misconnection	Low

Diagnostic Commands

```
show interface status
show interface GigabitEthernet 1/0/1 detail
show ip interface brief
show ip route | include 192.168.1.0
show spanning-tree summary
```

Resolution Steps

- Step 1: {'Step': '1', 'Action': 'Check physical connections and cables for damage or misconnection. Verify the fiber connection to the switch and the far-end device.'}
- Step 2: {'Step': '2', 'Action': '"Run the command 'show interface GigabitEthernet 1/0/1 detail' to check for any errors or alarms on the affected interface.'}
- Step 3: {'Step': '3', 'Action': '"Run the command 'show ip interface brief' to verify that the IP address is correctly assigned and configured.'}
- Step 4: {'Step': '4', 'Action': '"Run the command 'show ip route | include 192.168.1.0' to verify that the routing protocol is functioning correctly.'}
- Step 5: {'Step': '5', 'Action': '"Run the command 'show spanning-tree summary' to verify that the spanning tree is functioning correctly.'}
- Step 6: {'Step': '6', 'Action': '"If the root cause is a software issue, reload the switch using the command 'reload' or 'copy running-config startup-config'.'}

Post-Check Verification

```
show interface status
show interface GigabitEthernet 1/0/1 detail
show ip interface brief
show ip route | include 192.168.1.0
show spanning-tree summary
```