

Cisco Access Switch Bangalore KA-76 - ALARM_2414 Severity Critical SOP

Node: Cisco-Access-Bangalore-KA-76 | **Vendor:** Cisco | **Severity:** Critical | **Alarm Code:** ALARM_2414

Description

This SOP addresses the ALARM_2414 issue on Cisco Access Switch Bangalore KA-76, a critical alarm indicating a potential hardware failure.

Potential Root Causes

Cause	Probability
Hardware Failure: Power Supply Unit (PSU) or Fan Failure	High
Software Bug: Misconfigured or Malfunctioning Switch Software	Medium
Environmental Factors: Overheating or Power Outage	Low

Diagnostic Commands

```
show environment
show power inline power
show system resources
show tech-support
```

Resolution Steps

Step 1: {'Step': '1. Identify the affected switch and isolate it from the network', 'Action': "Use the 'show ip interface brief' command to identify the switch and isolate it from the network using the 'shutdown' command on the relevant interfaces."}

Step 2: {'Step': '2. Check the switch logs for error messages related to the alarm', 'Action': "Use the 'show logging' command to view the switch logs and identify error messages related to the ALARM_2414 issue."}

Step 3: {'Step': '3. Run the 'show environment' command to check for any hardware issues', 'Action': "Verify the switch temperature, power consumption, and other environmental factors using the 'show environment' command."}

Step 4: {'Step': '4. Replace the faulty PSU or fan (if hardware failure is confirmed)', 'Action': 'Replace the faulty PSU or fan with a new one and ensure it is properly seated and configured.'}

Step 5: {'Step': '5. Verify the switch software version and upgrade to the latest version (if software issue is suspected)', 'Action': "Use the 'show version' command to verify the switch software version and

upgrade to the latest version using the 'copy tftp' command."}

Post-Check Verification

```
show environment
show power inline power
show system resources
show version
show logging
```