

Cisco Access Switch Bangalore Node KA-76 Alarm Resolution SOP

Node: Cisco-Access-Bangalore-KA-76 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_5942

Description

This SOP outlines the steps to identify and resolve the ALARM_5942 warning on Cisco Access Switch Bangalore Node KA-76.

Potential Root Causes

Cause	Probability
Misconfigured VLAN trunking	High
Insufficient switch hardware resources	Medium
Software bug or glitch	Low

Diagnostic Commands

```
show vlan brief
show int trunk
show tech-support
show system resources
```

Resolution Steps

- Step 1: {'Step': 'Verify VLAN trunking configuration', 'Action': ['Verify VLAN trunking settings using the show vlan brief command.', 'Check for any misconfigured VLAN trunking settings.'], 'CLI_Commands': ['show vlan brief', 'show int trunk']}
- Step 2: {'Step': 'Check switch hardware resources', 'Action': ['Verify system resources using the show system resources command.', 'Check for any insufficient hardware resources.'], 'CLI_Commands': ['show system resources']}
- Step 3: {'Step': 'Backup and reload the switch', 'Action': ['Backup the switch configuration using the copy running-config startup-config command.', 'Reload the switch using the reload command.'], 'CLI_Commands': ['copy running-config startup-config', 'reload']}

Post-Check Verification

```
show vlan brief
show int trunk
```

```
show system resources
```