

Alarms and Troubleshooting SOP for Cisco Access Switch - Bangalore KA 76

Node: Cisco-Access-Bangalore-KA-76 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_6025

Description

Documentation of Alarm Code ALARM_6025 on Cisco Access Switch Node ID Cisco-Access-Bangalore-KA-76

Potential Root Causes

Cause	Probability
Incorrect Spanning Tree Configuration	High
Interface Loopback or Duplex Mismatch	Medium
Hardware Failure (Switch or Interface)	Low

Diagnostic Commands

```
show spanning-tree detail
show interfaces status
show interface brief | in duplex mismatch
show interface transceivers
```

Resolution Steps

- Step 1: {'Step': 'Verify spanning tree configuration and correct if necessary', 'Action': 'spanning-tree vlan root primary', 'CLI_Commands': 'show spanning-tree vlan '}
- Step 2: {'Step': 'Check for interface loopback or duplex mismatch', 'Action': 'shutdown interface ', 'CLI_Commands': 'show interfaces status'}
- Step 3: {'Step': 'Replace faulty switch or interface', 'Action': 'Remove and replace switch or interface', 'CLI_Commands': ''}

Post-Check Verification

```
show spanning-tree detail
show interfaces status
show interface brief | in duplex mismatch
show interface transceivers
```