

Cisco Access Switch Alarm Resolution SOP - ALARM_7278

Node: Cisco-Access-Bangalore-KA-76 | **Vendor:** Cisco | **Severity:** Minor | **Alarm Code:** ALARM_7278

Description

This Standard Operating Procedure (SOP) outlines the steps to resolve the ALARM_7278 alarm on the Cisco Access Switch Bangalore KA-76.

Potential Root Causes

Cause	Probability
Misconfigured VLAN settings	High
Faulty network interface	Medium
Overloaded switch resources	Low

Diagnostic Commands

```
show vlan brief
show interface status | exclude down
show process cpu sorted
show memory statistics
```

Resolution Steps

- Step 1: {'Step': 'Verify VLAN settings and correct if necessary', 'Action': 'Enter the following command: show vlan brief and verify that VLAN settings are correct.', 'CLI_Command': 'configure terminal\nvlan \nno shutdown'}
- Step 2: {'Step': 'Check network interface status and correct if necessary', 'Action': 'Enter the following command: show interface status | exclude down and verify that network interfaces are up.', 'CLI_Command': 'interface \nshutdown\nno shutdown'}
- Step 3: {'Step': 'Monitor switch CPU and memory usage', 'Action': 'Enter the following command: show process cpu sorted and show memory statistics to monitor switch resources.', 'CLI_Command': ''}

Post-Check Verification

```
show vlan brief
show interface status | exclude down
show process cpu sorted
```

```
show memory statistics
```