

Cisco Access Switch - ALARM_9774 Warning Severity Alarm Resolution SOP

Node: Cisco-Access-Bangalore-KA-76 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_9774

Description

This Standard Operating Procedure (SOP) outlines the steps to diagnose, resolve, and verify the fix for the ALARM_9774 warning severity alarm on the Cisco Access Switch node Cisco-Access-Bangalore-KA-76.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Misconfigured VLANs	Medium
Software Image Issues	Low

Diagnostic Commands

```
show processes cpu | exclude System
show vlan database
show version
show tech-support
```

Resolution Steps

Step 1: {'Step': '1', 'Action': 'Check CPU Utilization and adjust as necessary', 'Command': 'hw-module switch 1 process cpu-level adjust'}

Step 2: {'Step': '2', 'Action': 'Verify VLAN configuration', 'Command': 'show vlan database'}

Step 3: {'Step': '3', 'Action': 'Update software image if necessary', 'Command': 'install software force'}

Step 4: {'Step': '4', 'Action': 'Clear and re-synchronize the VLAN database', 'Command': 'clear vlan database'}

Post-Check Verification

```
show processes cpu | exclude System
show vlan database
show version
```

show tech-support