

Standard Operating Procedure for Alarm

ALARM_1807 on Cisco Access Switch Bangalore KA-80

Node: Cisco-Access-Bangalore-KA-80 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_1807

Description

Alarm ALARM_1807 on Cisco Access Switch Bangalore KA-80 indicates a major issue with the switch's hardware. The switch is experiencing a temperature-related hardware failure, potentially leading to system shutdown or data loss.

Potential Root Causes

Cause	Probability
Overheating of the switch due to poor airflow or malfunctioning fans	High
Faulty or loose connections within the switch	Medium
Inadequate temperature monitoring or configuration	Low

Diagnostic Commands

```
show env temperature
show sysmon status
show inventory
show module | include temperature
```

Resolution Steps

- Step 1: {'Step': '1. Power off the switch immediately to prevent further damage', 'Action': 'shutdown'}
- Step 2: {'Step': '2. Verify the temperature sensor and ensure proper airflow around the switch', 'Action': 'show env temperature'}
- Step 3: {'Step': '3. Inspect and replace faulty or loose connections within the switch', 'Action': 'show inventory'}
- Step 4: {'Step': '4. Configure temperature monitoring and alarms if necessary', 'Action': 'configure terminal\n temperature monitoring enable\n temperature alarm threshold'}
- Step 5: {'Step': '5. Power on the switch and verify the issue is resolved', 'Action': 'no shutdown'}

Post-Check Verification

```
show env temperature
```

```
show sysmon status  
show inventory  
show module | include temperature
```