

Cisco Access Switch Alarm Resolution SOP: ALARM_3511

Node: Cisco-Access-Bangalore-KA-80 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_3511

Description

This SOP outlines the steps to diagnose and resolve the ALARM_3511 on Cisco Access Switch Node ID: Cisco-Access-Bangalore-KA-80.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Incorrect Configuration	Medium
Hardware Failure	Low

Diagnostic Commands

```
show processes cpu
show system resources
show running-config
show startup-config
show boot variables
```

Resolution Steps

- Step 1: {'Step': 'Check CPU Utilization', 'Action': 'Run show processes cpu command to identify high CPU consuming processes.', 'CLI_Command': 'show processes cpu'}
- Step 2: {'Step': 'Verify Configuration', 'Action': 'Compare running-config and startup-config to ensure no syntax errors.', 'CLI_Command': 'show running-config | compare show startup-config'}
- Step 3: {'Step': 'Reset Switch', 'Action': 'Reset the switch using the reload command.', 'CLI_Command': 'reload'}
- Step 4: {'Step': 'Replace Hardware', 'Action': 'Replace the faulty hardware component.', 'Note': 'Please consult the switch manual for hardware replacement instructions.'}

Post-Check Verification

```
show system resources
```

```
show running-config | include
```