

Cisco-Access-Bangalore-KA-80 Major Alarm SOP: ALARM_4809

Node: Cisco-Access-Bangalore-KA-80 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_4809

Description

This SOP outlines the standard operating procedure for resolving the major alarm ALARM_4809 on Cisco-Access-Bangalore-KA-80, a Cisco Access Switch.

Potential Root Causes

Cause	Probability
High CPU utilization due to software bugs or misconfiguration	High
Hardware issues such as temperature fluctuations or power supply problems	Medium
Interoperability issues with neighboring devices or network components	Low

Diagnostic Commands

```
show processes cpu | exclude System
show system resource
show interface status
show stack
```

Resolution Steps

- Step 1: {'Step': 'Step 1: Check CPU utilization and system resources', 'Action': "Run 'show processes cpu | exclude System' and 'show system resource' commands to identify high CPU utilization and resource bottlenecks."}
- Step 2: {'Step': 'Step 2: Verify interface status and troubleshoot physical connections', 'Action': "Run 'show interface status' command to verify interface status and troubleshoot physical connections."}
- Step 3: {'Step': 'Step 3: Check for software bugs or misconfiguration', 'Action': "Run 'show version' command to verify software version and configuration. Check for any known bugs or issues."}
- Step 4: {'Step': 'Step 4: Perform hardware troubleshooting', 'Action': "Check for any physical issues such as temperature fluctuations or power supply problems. Run 'show environment' command to verify environmental conditions."}
- Step 5: {'Step': 'Step 5: Troubleshoot interoperability issues', 'Action': "Run 'show neighbors' command to verify connections with neighboring devices. Check for any configuration issues or miscommunication."}

Post-Check Verification

```
show processes cpu | exclude System  
show system resource  
show interface status
```