

Cisco Access Switch Bangalore KA-80 SOP for Alarm ALARM_7723

Node: Cisco-Access-Bangalore-KA-80 | **Vendor:** Cisco | **Severity:** Critical | **Alarm Code:** ALARM_7723

Description

This SOP outlines the steps to diagnose and resolve the ALARM_7723 on the Cisco Access Switch Bangalore KA-80.

Potential Root Causes

Cause	Probability
High CPU Usage	High
STP Loop detected	Medium
Software bug or configuration issue	Low

Diagnostic Commands

```
show process cpu | exclude System
show spanning-tree detail
show running-config | include
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU usage and identify the processes consuming high CPU', 'Action': 'Run show process cpu | exclude System and analyze the output.', 'CLI_Commands': ['show process cpu | exclude System']}
- Step 2: {'Step': '2. Verify STP topology and identify any potential loops', 'Action': 'Run show spanning-tree detail and analyze the output.', 'CLI_Commands': ['show spanning-tree detail']}
- Step 3: {'Step': '3. Review and update the configuration if necessary', 'Action': 'Run show running-config | include and verify the configuration.', 'CLI_Commands': ['show running-config | include ']}
- Step 4: {'Step': '4. Perform a software reload if none of the above steps resolve the issue', 'Action': 'Run reload command.', 'CLI_Commands': ['reload']}

Post-Check Verification

```
show process cpu | exclude System
show spanning-tree detail
show running-config | include
```