

Standard Operating Procedure: Cisco Access Switch Bangalore KA 80 Alarm ALARM_8006

Node: Cisco-Access-Bangalore-KA-80 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_8006

Description

This SOP outlines the steps to diagnose, resolve, and verify the fix for the ALARM_8006 (Warning) on Cisco Access Switch Bangalore KA 80.

Potential Root Causes

Cause	Probability
High CPU usage on the switch due to excessive CPU-intensive processes.	High
Misconfigured QoS policies causing network congestion.	Medium
Software bugs or glitches causing instability on the switch.	Low

Diagnostic Commands

```
show processes cpu
show cpu resource
show qos policy-map interface
show run | inc qos
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU usage and resource allocation on the switch.', 'Action': 'Run the show processes cpu and show cpu resource commands to identify the cause of high CPU usage.'}
- Step 2: {'Step': '2. Verify QoS policy configuration and settings.', 'Action': 'Run the show qos policy-map interface and show run | inc qos commands to verify QoS policy configuration and settings.'}
- Step 3: {'Step': '3. Clear and reconfigure QoS policies if necessary.', 'Action': 'Clear existing QoS policies and reconfigure them using the config t and qos policy-map interface commands.'}
- Step 4: {'Step': '4. Upgrade or patch the switch software if necessary.', 'Action': 'Run the show version command to verify the switch software version and upgrade or patch it if necessary using the upgrade and copy commands.'}

Post-Check Verification

```
show clock
show version
```

```
show qos policy-map interface  
show run | inc qos
```