

Standard Operating Procedure for ALARM_2232 on Cisco-Access-Chennai-TN-100

Node: Cisco-Access-Chennai-TN-100 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_2232

Description

ALARM_2232 indicates a Major alarm on Cisco-Access-Chennai-TN-100, a Cisco Access Switch. This SOP outlines the diagnostic and resolution steps for the root causes of this alarm.

Potential Root Causes

Cause	Probability
High CPU Utilization due to Spanning Tree Protocol (STP) Flaps	High
Incorrect VLAN Configuration	Medium
Faulty or Misconfigured Network Interface Card (NIC)	Low

Diagnostic Commands

```
show spanning-tree summary
show spanning-tree detail
show vlan
show interface
show ip interface brief
```

Resolution Steps

- Step 1: {'Step': '1. Check for STP Flaps', 'Actions': ['Use the show spanning-tree summary command to verify STP status.', 'If STP is flapping, use the show spanning-tree detail command to identify the root cause.', 'Run the command 'spanning-tree portfast bpduguard default' to enable PortFast and BPDU Guard on all ports.', 'Verify the change with the command 'show spanning-tree summary'.']}
- Step 2: {'Step': '2. Verify VLAN Configuration', 'Actions': ['Use the show vlan command to verify VLAN configuration.', 'Check for any duplicate or overlapping VLAN IDs.', 'If necessary, reconfigure VLANs using the command 'vlan name '.', 'Verify the change with the command 'show vlan'.']}
- Step 3: {'Step': '3. Inspect Network Interface Cards (NICs)', 'Actions': ['Inspect the NICs for any physical damage or configuration issues.', 'Run the command 'show interface ' to verify the interface status.', 'If necessary, reseal or replace the NIC.', 'Verify the change with the command 'show interface '.']}

Post-Check Verification

```
show spanning-tree summary
```

```
show vlan
show interface
show ip interface brief
```