

SOP: Cisco Access Switch Chennai TN-100 - Alarm 2464

Node: Cisco-Access-Chennai-TN-100 | **Vendor:** Cisco | **Severity:** Critical | **Alarm Code:** ALARM_2464

Description

This is a standard operating procedure for addressing the critical alarm ALARM_2464 on the Cisco Access Switch Chennai TN-100. The alarm indicates a potential hardware or software issue that requires immediate attention.

Potential Root Causes

Cause	Probability
Power Supply Unit (PSU) failure	High
Fan failure	Medium
Hardware component failure (e.g., ASIC, CPU, or memory)	Medium
Software configuration issue	Low

Diagnostic Commands

```
show power inline
show environment
show version
show boot
show log
debug interface
```

Resolution Steps

- Step 1: {'Step': 'Replace the PSU (if faulty)', 'Action': "Use the 'power inline' command to identify the PSU and replace it with a spare unit"}
- Step 2: {'Step': 'Replace the fan (if faulty)', 'Action': "Use the 'environment' command to identify the fan and replace it with a spare unit"}
- Step 3: {'Step': 'Replace the hardware component (if faulty)', 'Action': "Use the 'show version' and 'show boot' commands to identify the component and replace it with a spare unit"}
- Step 4: {'Step': 'Verify software configuration', 'Action': "Use the 'show log' command to verify software configuration and make necessary adjustments"}

Step 5: {'Step': 'Reset the switch (if necessary)', 'Action': "Use the 'reset' command to reset the switch to its default configuration"}

Post-Check Verification

```
show power inline
show environment
show version
show boot
show log
```