

Cisco Access Switch Node Chennai-TN-100 Alarm Response SOP

Node: Cisco-Access-Chennai-TN-100 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_3840

Description

Response to ALARM_3840 on Node ID: Cisco-Access-Chennai-TN-100 - A major alarm indicating a critical issue on the Cisco Access Switch.

Potential Root Causes

Cause	Probability
Power Supply Failure	High
Hardware Component Malfunction	Medium
Software Configuration Error	Low

Diagnostic Commands

```
show power inline status
show environment all
show version
show running-config
```

Resolution Steps

Step 1: {'Step': '1. Identify the failing power supply', 'Action': "Run 'show power inline status' to identify the failing power supply"}

Step 2: {'Step': '2. Replace the failing power supply', 'Action': "Use the 'power inline replace' command to replace the failing power supply"}

Step 3: {'Step': '3. Verify the configuration', 'Action': "Run 'show running-config' to verify the configuration"}

Step 4: {'Step': '4. Save the changes', 'Action': "Use the 'copy running-config startup-config' command to save the changes"}

Step 5: {'Step': '5. Monitor the system', 'Action': 'Continuously monitor the system to ensure the issue is resolved'}

Post-Check Verification

```
show clock
```

```
show version
show environment all
show power inline status
```