

Cisco Access Switch Alarm Resolution SOP

(ALARM_7910)

Node: Cisco-Access-Chennai-TN-100 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_7910

Description

Major Alarm on Cisco Access Switch (Node ID: Cisco-Access-Chennai-TN-100) with Alarm Code ALARM_7910.

Potential Root Causes

Cause	Probability
Power Supply Failure	High
Temperature Sensors Fault	Medium
ASIC (Application-Specific Integrated Circuit) Failure	Low

Diagnostic Commands

```
show environment
show power
show temperature
show module
show asp table asp
```

Resolution Steps

- Step 1: {'Step': '1. Power Cycle the Switch', 'Action': 'Power off the switch, wait for 30 seconds, and then power it back on.', 'Command': ''}
- Step 2: {'Step': '2. Replace Faulty Power Supply', 'Action': 'Replace the power supply with a new one, and ensure it is properly seated.', 'Command': 'replace power-supply '}
- Step 3: {'Step': '3. Inspect Temperature Sensors', 'Action': 'Verify the temperature sensors are properly connected and functioning correctly.', 'Command': 'show temperature'}
- Step 4: {'Step': '4. Replace Faulty ASIC', 'Action': 'Replace the ASIC with a new one, and ensure it is properly seated.', 'Command': 'replace asic '}

Post-Check Verification

```
show environment
show power
```

```
show temperature
show module
show asp table asp
```