

Cisco Access Switch Alarm SOP: ALARM_8960

Node: Cisco-Access-Chennai-TN-100 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_8960

Description

This SOP outlines the steps to diagnose and resolve a Major alarm on the Cisco Access Switch, Node ID: Cisco-Access-Chennai-TN-100, with Alarm Code: ALARM_8960.

Potential Root Causes

Cause	Probability
High CPU utilization due to software bugs or misconfiguration	High
Incorrect configuration or misaligned VLANs	Medium
Hardware failure or malfunction	Low

Diagnostic Commands

```
show process cpu
show startup-config
show running-config
show vlan
show interface status
```

Resolution Steps

Step 1: {'Step': 'Check CPU utilization and identify any software bugs or misconfiguration.', 'Action': "Run 'show process cpu' command and analyze the output."}

Step 2: {'Step': 'Verify VLAN configurations and alignment.', 'Action': "Run 'show vlan' command and check for any misaligned VLANs."}

Step 3: {'Step': 'Verify switch configuration and identify any misconfigurations.', 'Action': "Run 'show startup-config' and 'show running-config' commands to verify switch configuration."}

Step 4: {'Step': 'Perform a hardware reset or power cycle the switch if necessary.', 'Action': "Run 'power-on' or 'reload' command to reset the switch."}

Step 5: {'Step': 'Check for hardware failure or malfunction.', 'Action': "Run 'show interface status' command to verify interface status."}

Post-Check Verification

```
show process cpu
```

```
show vlan
show interface status
```