

SOP: Resolving ALARM_9373 on Cisco-Access-Chennai-TN-100

Node: Cisco-Access-Chennai-TN-100 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_9373

Description

This SOP outlines the steps to resolve a major alarm (ALARM_9373) on Cisco-Access-Chennai-TN-100, a Cisco Access Switch.

Potential Root Causes

Cause	Probability
Physical Interface Failure	High
Software Bug	Medium
Cable Damage	Low

Diagnostic Commands

```
show int GigabitEthernet 0/0/0
show ip interface brief
show log | include ALARM_9373
show tech-support
```

Resolution Steps

- Step 1: {'Step': '1. Physically inspect the interface for any signs of damage or malfunction.', 'Action': ''}
- Step 2: {'Step': '2. Run the following command to verify the interface configuration:', 'Action': 'show running-config interface GigabitEthernet 0/0/0'}
- Step 3: {'Step': '3. If the issue persists, perform a soft reset of the switch:', 'Action': 'reload in 15'}
- Step 4: {'Step': '4. If the issue still persists, replace the faulty interface card.', 'Action': ''}

Post-Check Verification

```
show ip interface brief
show log | include ALARM_9373
show tech-support
```