

SOP for Major Alarm ALARM_1974 on Cisco Access Switch Chennai-TN-104

Node: Cisco-Access-Chennai-TN-104 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_1974

Description

This SOP outlines the steps to diagnose, resolve, and verify the fix for Major Alarm ALARM_1974 on Cisco Access Switch Chennai-TN-104.

Potential Root Causes

Cause	Probability
High CPU Utilization due to Spanning Tree Protocol (STP) Flapping	High
Misconfigured VLANs or Trunks	Medium
Hardware Fault or Failure	Low

Diagnostic Commands

```
show spanning-tree detail
show vlan brief
show interface trunk
show process cpu history
show tech-support
```

Resolution Steps

- Step 1: {'Step': 'Check and clear Spanning Tree Protocol (STP) Flapping', 'Action': 'use the command "clear spanning-tree counters" followed by "no spanning-tree vlan "'}
- Step 2: {'Step': 'Verify VLAN configurations and trunk settings', 'Action': 'run the command "show vlan brief" and "show interface trunk" to verify VLAN and trunk configurations'}
- Step 3: {'Step': 'Replace or repair faulty hardware', 'Action': 'identify and replace or repair the faulty hardware component'}

Post-Check Verification

```
show spanning-tree detail
show vlan brief
show interface trunk
show process cpu history
```