

Cisco Access Switch Alarm Resolution SOP - ALARM_7336

Node: Cisco-Access-Chennai-TN-104 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_7336

Description

Warning: Interface Overload on Cisco Access Switch (Cisco-Access-Chennai-TN-104)

Potential Root Causes

Cause	Probability
High CPU utilization due to software issues	High
Misconfigured interface settings	Medium
Physical interface issues (e.g., cable problems)	Low

Diagnostic Commands

```
show processes cpu | include Packet
show interface | include Overload
show interface | include errors
```

Resolution Steps

- Step 1: {'Step': "Verify interface settings using 'show running-config' and correct if necessary", 'Command': 'show running-config | include interface '}
- Step 2: {'Step': "Verify interface status using 'show interface' and correct if necessary", 'Command': 'show interface '}
- Step 3: {'Step': "Check CPU utilization using 'show processes cpu' and address software issues if necessary", 'Command': 'show processes cpu | include Packet'}
- Step 4: {'Step': "Check for physical interface issues using 'show interface | include errors'", 'Command': 'show interface | include errors'}

Post-Check Verification

```
show processes cpu | include Packet
show interface | include Overload
show interface | include errors
```