

Cisco Access Switch - Minor Alarm Resolution SOP

Node: Cisco-Access-Chennai-TN-104 | **Vendor:** Cisco | **Severity:** Minor | **Alarm Code:** ALARM_8736

Description

This Standard Operating Procedure (SOP) outlines the steps to resolve a minor alarm on Cisco Access Switch Node ID: Cisco-Access-Chennai-TN-104.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Incorrect Configuration	Medium
Hardware Failure	Low

Diagnostic Commands

```
show processes cpu | include CPU
show system resource | include Memory
show interface status
show running-config
```

Resolution Steps

- Step 1: {'Step': 'Verify CPU Utilization', 'Action': "Use the command 'show processes cpu | include CPU' to check if CPU utilization is within normal limits."}
- Step 2: {'Step': 'Check Configuration', 'Action': "Use the command 'show running-config' to verify if the configuration is correct."}
- Step 3: {'Step': 'Check Hardware', 'Action': "Use the command 'show interface status' to check for any hardware issues."}
- Step 4: {'Step': 'Reset Configuration', 'Action': "Use the command 'reload' to reset the switch to factory defaults."}

Post-Check Verification

```
show processes cpu | include CPU
show system resource | include Memory
show interface status
show running-config
```