

Cisco Access Switch Alarm Resolution SOP: ALARM_1947

Node: Cisco-Access-Chennai-TN-106 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_1947

Description

This SOP outlines the steps to diagnose, resolve, and verify the fix for Cisco Access Switch alarm ALARM_1947, which indicates a Warning condition on the Cisco-Access-Chennai-TN-106 device.

Potential Root Causes

Cause	Probability
Physical interface failure or misconfiguration	High
Software bug or misconfiguration	Medium
Environmental or power issues	Low

Diagnostic Commands

```
show interface status
show interface detail
show running-config
show version
debug interface
```

Resolution Steps

- Step 1: {'Step': 'Check physical connections and cables', 'Action': 'Verify that all cables are securely connected to the correct ports.'}
- Step 2: {'Step': 'Verify interface configuration', 'Action': '"Check the interface configuration using the 'show interface ' command.'}
- Step 3: {'Step': 'Check for software issues', 'Action': 'Verify that the software is up-to-date and there are no known bugs or issues.'}
- Step 4: {'Step': 'Clear interface counters', 'Action': '"Use the 'clear counters' command to clear the interface counters.'}
- Step 5: {'Step': 'Save the configuration', 'Action': '"Save the configuration using the 'copy running-config startup-config' command.'}

Post-Check Verification

```
show interface status  
show interface detail  
show running-config  
show version
```