

Standard Operating Procedure: Alarm ALARM_4168 on Cisco-Access-Chennai-TN-106

Node: Cisco-Access-Chennai-TN-106 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_4168

Description

Alarm ALARM_4168 on Cisco-Access-Chennai-TN-106 indicates a potential issue with the switch's stacking configuration.

Potential Root Causes

Cause	Probability
Stacking configuration issue	High
Incorrect VLAN configuration	Medium
Hardware failure on one of the stack members	Low

Diagnostic Commands

```
show switch stack
show vlan
show interface status
show tech-support
```

Resolution Steps

- Step 1: {'Step': 'Verify the stacking configuration', 'Action': "Run the command 'show switch stack' to check the stack status.", 'CLI_Commands': 'show switch stack'}
- Step 2: {'Step': 'Check VLAN configuration', 'Action': "Verify VLAN configuration using the command 'show vlan'.", 'CLI_Commands': 'show vlan'}
- Step 3: {'Step': 'Check interface status', 'Action': "Use the command 'show interface status' to verify interface status.", 'CLI_Commands': 'show interface status'}
- Step 4: {'Step': 'Collect technical support information', 'Action': "Run the command 'show tech-support' to collect technical support information.", 'CLI_Commands': 'show tech-support'}
- Step 5: {'Step': 'Reset the switch', 'Action': "Reset the switch using the command 'reset system' if the issue persists.", 'CLI_Commands': 'reset system'}

Post-Check Verification

```
show switch stack
show vlan
show interface status
show tech-support
```