

Resolution of Major Alarm ALARM_9579 on Cisco Access Switch Chennai TN-96

Node: Cisco-Access-Chennai-TN-96 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_9579

Description

This SOP outlines the steps to diagnose and resolve the Major Alarm ALARM_9579 on Cisco Access Switch Chennai TN-96.

Potential Root Causes

Cause	Probability
High CPU utilization due to excessive packet processing	High
Misconfigured VLANs or trunks	Medium
Hardware failure	Low

Diagnostic Commands

```
show processes cpu sorted
show interfaces trunk
show run | include vlan
show version
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU utilization', 'Action': "Issue the command 'show processes cpu sorted' to determine if CPU utilization is high."}
- Step 2: {'Step': '2. Verify VLAN and trunk configurations', 'Action': "Use the 'show interfaces trunk' and 'show run | include vlan' commands to verify correct VLAN and trunk configurations."}
- Step 3: {'Step': '3. Check for hardware issues', 'Action': "Use the 'show version' command to verify the switch's hardware and software configurations."}
- Step 4: {'Step': '4. Adjust CPU-intensive processes (if necessary)', 'Action': "Issue the command 'process cpu-limit ' to adjust the CPU utilization limit."}
- Step 5: {'Step': '5. Correct misconfigured VLANs or trunks', 'Action': "Use the 'interface ' command to correct VLAN and trunk configurations."}
- Step 6: {'Step': '6. Replace hardware (if necessary)', 'Action': 'Replace the switch with a new one or contact Cisco support for further assistance.'}

Post-Check Verification

```
show processes cpu sorted  
show interfaces trunk  
show run | include vlan  
show version
```