

Cisco Access Switch Delhi NCR 16 Alarm Resolution SOP

Node: Cisco-Access-Delhi-NCR-16 | **Vendor:** Cisco | **Severity:** Minor | **Alarm Code:** ALARM_4459

Description

This SOP outlines the steps to resolve the ALARM_4459: Minor error on Cisco Access Switch Delhi NCR 16.

Potential Root Causes

Cause	Probability
Incorrect configuration of Spanning Tree Protocol (STP)	Medium
Hardware failure of the switch's CPU	Low
Insufficient memory on the switch	Medium

Diagnostic Commands

```
show spanning-tree detail
show system resources
show tech-support
```

Resolution Steps

- Step 1: {'Step': 'Verify STP configuration', 'Action': "Check the STP configuration on the switch using 'show spanning-tree detail' command"}
- Step 2: {'Step': 'Check system resources', 'Action': "Verify the available memory and CPU usage on the switch using 'show system resources' command"}
- Step 3: {'Step': 'Reset the switch', 'Action': 'Restart the switch to resolve the issue'}
- Step 4: {'Step': 'Replace the faulty hardware', 'Action': "Replace the switch's CPU if it is found to be faulty"}
- Step 5: {'Step': 'Increase memory on the switch', 'Action': 'Add more memory to the switch to resolve the issue'}

Post-Check Verification

```
show spanning-tree detail
show system resources
show tech-support
```