

Cisco Access Switch Delhi-NCR-16 Alarm Resolution SOP

Node: Cisco-Access-Delhi-NCR-16 | **Vendor:** Cisco | **Severity:** Critical | **Alarm Code:** ALARM_5128

Description

This SOP outlines the steps to diagnose and resolve a critical alarm ALARM_5128 on Cisco Access Switch Delhi-NCR-16.

Potential Root Causes

Cause	Probability
High CPU Utilization due to excessive routing protocol traffic	High
Incorrect configuration of spanning tree protocol	Medium
Hardware failure of the switch	Low

Diagnostic Commands

```
show processes cpu | exclude System
show spanning-tree detail
show tech-support
```

Resolution Steps

- Step 1: {'Step': 'Verify CPU utilization and identify the process causing the high utilization', 'Action': "Run the command 'show processes cpu | exclude System' and analyze the output"}
- Step 2: {'Step': 'Verify spanning tree configuration and correct any errors', 'Action': "Run the command 'show spanning-tree detail' and correct any errors in the configuration"}
- Step 3: {'Step': 'Replace the switch with a new one if hardware failure is suspected', 'Action': "Run the command 'show tech-support' to gather diagnostic information and contact the manufacturer for further assistance"}

Post-Check Verification

```
show processes cpu | exclude System
show spanning-tree detail
show ip interface brief
```