

Cisco Access Switch - Alarm ALARM_6939 SOP

Node: Cisco-Access-Delhi-NCR-16 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_6939

Description

Resolving Major Alarm ALARM_6939 on Cisco Access Switch Cisco-Access-Delhi-NCR-16

Potential Root Causes

Cause	Probability
Overtemperature in the switch chassis	High
Incorrect power supply configuration	Medium
Faulty switch fan	Low

Diagnostic Commands

```
show environment
show power
show inventory
```

Resolution Steps

- Step 1: {'Step': 'Check switch temperature and power supply configuration', 'Action': "Run 'show environment' and 'show power' commands to verify switch temperature and power supply configuration.", 'CLI_Commands': ['show environment', 'show power']}
- Step 2: {'Step': 'Verify power supply configuration and replace if necessary', 'Action': 'Check power supply configuration and replace if necessary.', 'CLI_Commands': ['show power', 'power redundancy-mode ?', 'power redundancy- mode hot-standby']}
- Step 3: {'Step': 'Replace faulty switch fan if necessary', 'Action': 'Replace faulty switch fan if necessary.', 'CLI_Commands': []}

Post-Check Verification

```
show environment
show power
show inventory
```