

SOP for Alarm Code ALARM_2971 on Cisco Access Switch Delhi NCR-18

Node: Cisco-Access-Delhi-NCR-18 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_2971

Description

This SOP outlines the steps to diagnose and resolve the Alarm Code ALARM_2971 on Cisco Access Switch Delhi NCR-18.

Potential Root Causes

Cause	Probability
Link down or misconfigured interface	High
Spanning Tree Protocol (STP) issue	Medium
Hardware failure or faulty card	Low

Diagnostic Commands

```
show interface | include Up/Down
show spanning-tree detail
show module | include Faulty
```

Resolution Steps

- Step 1: {'Step': 'Verify interface status', 'Action': "Execute the command 'show interface | include Up/Down' to check if the interface is up or down."}
- Step 2: {'Step': 'Configure interface', 'Action': "Execute the command 'interface | no shutdown' to bring the interface up."}
- Step 3: {'Step': 'Verify STP status', 'Action': "Execute the command 'show spanning-tree detail' to check for any STP issues."}
- Step 4: {'Step': 'Reset STP', 'Action': "Execute the command 'spanning-tree reset' to reset the STP."}
- Step 5: {'Step': 'Verify module status', 'Action': "Execute the command 'show module | include Faulty' to check for any hardware issues."}
- Step 6: {'Step': 'Replace faulty card', 'Action': 'Replace the faulty card with a new one.'}

Post-Check Verification

```
show interface | include Up/Down
show spanning-tree detail
```

```
show module | include Faulty
```