

Standard Operating Procedure (SOP) for Cisco-Access-Delhi-NCR-18

Node: Cisco-Access-Delhi-NCR-18 | **Vendor:** Cisco | **Severity:** Critical | **Alarm Code:** ALARM_9613

Description

Critical Alarm: ALARM_9613 - High CPU Utilization on Cisco Access Switch

Potential Root Causes

Cause	Probability
High CPU utilization due to software bugs	High
Misconfigured switch settings	Medium
Hardware issues with the switch	Low

Diagnostic Commands

```
show processes cpu
show system resources
show interface
```

Resolution Steps

Step 1: { 'Step': 'Restart the switch', 'Description': 'Try restarting the switch to clear any transient issues', 'Commands': ['reload'] }

Step 2: { 'Step': 'Check and adjust switch settings', 'Description': 'Verify and adjust the switch settings to ensure they are not causing high CPU utilization', 'Commands': ['show running-config', 'config t', 'no command', 'exit'] }

Step 3: { 'Step': 'Upgrade switch software', 'Description': 'Check for software updates and upgrade the switch to the latest version', 'Commands': ['show version', 'archive download-sw /force-reload', 'copy tftp: flash:'] }

Post-Check Verification

```
show processes cpu
show system resources
show interface
```