

Cisco Access Switch - ALARM_2729 Alarm Handling SOP

Node: Cisco-Access-Delhi-NCR-20 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_2729

Description

This SOP outlines the steps to identify, diagnose, and resolve the Cisco-Access-Delhi-NCR-20 Access Switch's ALARM_2729 alarm, which is a Major Severity alarm.

Potential Root Causes

Cause	Probability
Misconfigured VLAN or VTP settings	High
Hardware failure or malfunction	Medium
Software issues or bugs	Low

Diagnostic Commands

```
show vtp status
show vlan
show spanning-tree summary
show interface status
show tech-support
```

Resolution Steps

- Step 1: {'Step': 'Check VTP status and configuration', 'Action': "Run 'show vtp status' and verify VTP mode and domain name", 'CLI_Command': 'show vtp status'}
- Step 2: {'Step': 'Verify VLAN configuration', 'Action': "Run 'show vlan' and verify VLAN database", 'CLI_Command': 'show vlan'}
- Step 3: {'Step': 'Check spanning tree configuration', 'Action': "Run 'show spanning-tree summary' and verify spanning tree mode", 'CLI_Command': 'show spanning-tree summary'}
- Step 4: {'Step': 'Check interface status', 'Action': "Run 'show interface status' and verify interface status", 'CLI_Command': 'show interface status'}
- Step 5: {'Step': 'Collect technical support information', 'Action': "Run 'show tech-support' and collect output", 'CLI_Command': 'show tech-support'}
- Step 6: {'Step': 'Reset or replace hardware', 'Action': 'Reset or replace hardware component, if hardware failure is confirmed', 'CLI_Command': ''}

Step 7: {'Step': 'Reconfigure VLAN or VTP settings', 'Action': 'Reconfigure VLAN or VTP settings, if misconfiguration is confirmed', 'CLI_Command': 'config t; vlan database; vlan name '}

Post-Check Verification

```
show vtp status
show vlan
show spanning-tree summary
show interface status
show tech-support
```