

Standard Operating Procedure for Alarm

ALARM_1000 on Cisco Access Switch Delhi-NCR-26

Node: Cisco-Access-Delhi-NCR-26 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_1000

Description

Alarm ALARM_1000 is triggered on Cisco Access Switch Delhi-NCR-26 due to a warning condition.

Potential Root Causes

Cause	Probability
High CPU utilization due to excessive packet processing	High
Insufficient memory allocated to the switch	Medium
Misconfigured Quality of Service (QoS) settings	Low

Diagnostic Commands

```
show processes cpu | exclude System
show memory | exclude buffers
show mls qos map all
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU utilization and memory allocation', 'Action': 'Use the diagnostic commands to identify the root cause of the issue'}
- Step 2: {'Step': '2. Adjust CPU utilization by reducing packet processing or allocating more resources', 'Action': "Use the 'process cpu-priority' command to adjust CPU utilization"}
- Step 3: {'Step': '3. Allocate additional memory to the switch if necessary', 'Action': "Use the 'memory allocation' command to allocate additional memory"}
- Step 4: {'Step': '4. Review and adjust QoS settings if misconfigured', 'Action': "Use the 'mls qos' command to review and adjust QoS settings"}

Post-Check Verification

```
show processes cpu | exclude System
show memory | exclude buffers
show mls qos map all
```