

Cisco Access Switch Alarm SOP: ALARM_1868

Node: Cisco-Access-Delhi-NCR-26 | **Vendor:** Cisco | **Severity:** Minor | **Alarm Code:** ALARM_1868

Description

Minor alarm triggered on Cisco-Access-Delhi-NCR-26. ALARM_1868 indicates a potential misconfiguration or hardware issue.

Potential Root Causes

Cause	Probability
Misconfigured VLAN or port settings	Medium
Faulty or failing hardware component	Low
Interoperability issues with neighboring devices	Medium

Diagnostic Commands

```
show version
show interface status
show vlan brief
show running-config
show tech-support
```

Resolution Steps

- Step 1: {'Step': 'Verify VLAN and port configurations', 'Action': 'Run show vlan brief and show interface status commands to ensure correct configurations'}
- Step 2: {'Step': 'Check for hardware issues', 'Action': 'Run show tech-support to identify potential hardware problems'}
- Step 3: {'Step': 'Reconfigure VLAN and port settings (if necessary)', 'Action': 'Use the configure terminal command to make changes'}
- Step 4: {'Step': 'Verify interoperability with neighboring devices', 'Action': 'Run show interface status and show tech-support commands to identify any issues'}

Post-Check Verification

```
show vlan brief
show interface status
show running-config
```