

SOP - Cisco Access Switch ALARM_5085 Major Alarm on Node ID: Cisco-Access-Kolkata-WB-112

Node: Cisco-Access-Kolkata-WB-112 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_5085

Description

This SOP outlines the steps to diagnose and resolve the Major ALARM_5085 on Cisco-Access-Kolkata-WB-112, an Access Switch running Cisco firmware.

Potential Root Causes

Cause	Probability
High CPU usage due to stuck processes	High
Misconfigured spanning tree protocol	Medium
Physical layer issues on uplink ports	Low

Diagnostic Commands

```
show processes cpu | include CPU
show spanning-tree summary
show interface status | include uplink
```

Resolution Steps

- Step 1: {'Step': 'Restart the switch to clear stuck processes', 'CLI_Command': 'reload'}
- Step 2: {'Step': 'Verify and correct spanning tree configuration', 'CLI_Command': 'show spanning-tree detail'}
- Step 3: {'Step': 'Physically inspect uplink ports and replace if necessary', 'Action': 'Physical inspection and replacement of faulty hardware'}

Post-Check Verification

```
show processes cpu | include CPU
show spanning-tree summary
show interface status | include uplink
```