

Alarm Resolution SOP for Cisco Access Switch - ALARM_6848

Node: Cisco-Access-Kolkata-WB-112 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_6848

Description

This SOP outlines the steps to resolve the ALARM_6848 on Cisco Access Switch Node ID: Cisco-Access-Kolkata-WB-112.

Potential Root Causes

Cause	Probability
Invalid VLAN configuration	Medium
Misconfigured port settings	High
Hardware failure	Low

Diagnostic Commands

```
show vlan
show interface status
show run | include vlan
debug ilpower
```

Resolution Steps

- Step 1: {'Step': 'Verify VLAN configuration', 'Action': 'Run show vlan command and verify VLAN configuration. Make sure VLANs are properly configured.', 'CLI_Commands': ['show vlan']}
- Step 2: {'Step': 'Check port settings', 'Action': 'Run show interface status command and verify port settings. Make sure ports are properly configured.', 'CLI_Commands': ['show interface status']}
- Step 3: {'Step': 'Check for hardware failure', 'Action': 'Run debug ilpower command and verify power supply status. If power supply is failed, replace it.', 'CLI_Commands': ['debug ilpower']}

Post-Check Verification

```
show vlan
show interface status
show run | include vlan
```